## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,842,984 B1

DATED

: January 18, 2005

INVENTOR(S) : Grant et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6,

Line 3, should read "to said flange rests within said interior wall of said cutting"

Signed and Sealed this

Third Day of May, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office